



JON M. HUNTSMAN, JR.

Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
October 7, 2005

Supervisor 10027

Mine Name: Black Ridge 1

Operator Name: Thirstystone Resources, Inc.
860 East 19th Street
Tucson, Arizona 85719-6615

Permit number: S/053/027

Inspection Date: Sept. 28, 2005

Time: 0700

Inspector(s): Doug Jensen

Other Participants: None

Mine Status: Inactive

Weather: Sunny, cool

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This site was inspected while I was in the area.

Inspection Summary:

The site has remained unchanged since my inspection in February of this year. There has been no further flooding in the area. The mining activities at the site are located above the drainage; therefore, is not being impacted by the flooding. Access into the site down the drainage remains blocked with several big rocks.

No photos or GPS data were gathered during this visit.

Conclusions and Recommendations:

I will continue to monitor the site when I am in the area.

Inspector's Signature Doug Jensen

Date: October 7, 2005

DJ:jb

cc: Thirstystone Resources, Inc., Operator
Rody Cox, BLM, St George FO (UTU- 68868)

O:\M053-Washington\S0530027-BlackRidge1\inspections\insp-09282005.doc